

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-31270

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Dugan Production Corp.	Contact	Rodger Mullins
Address	P. O. Box 420, Farmington, NM 87499-0420	Telephone No.	(505)325-1821
Facility Name	State Com #90S	Facility Type	

Surface Owner	State	Mineral Owner	State	Lease No.	LG-0038-1
---------------	-------	---------------	-------	-----------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	16	32N	12W	1940	North	1270	West	San Juan

Latitude 36.98805 Longitude 108.10472

NATURE OF RELEASE

Type of Release	water	Volume of Release	100 bbl	Volume Recovered	50 bbls
Source of Release	water tank overflowed	Date and Hour of Occurrence	6/25/07 early a.m.	Date and Hour of Discovery	6/25/07 @ 7:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Aztec Office NMOCD - Brandon Powell		
By Whom?	Rodger Mullins	Date and Hour	6/25/07 @ 11:00 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RCVD JUN28'07
OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

Water wasn't pulled from tank as ordered. Contaminated dirt hauled off. New dirt brought in.

Describe Area Affected and Cleanup Action Taken.*

Water in berm, water went under berm, across south side of location and onto dirt road. Contaminated dirt hauled off, new dirt brought in.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Rodger Mullins		Approved by District Supervisor:  For: Charlie Perrin	
Title: Production Foreman		Approval Date: 6-28-07	Expiration Date:
E-mail Address: rmullins@duganproduction.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 27, 2007 Phone: (505)325-1821			

* Attach Additional Sheets If Necessary

n BP0719442463