



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 2-17-10 Operator Dugan Production API # 30-0 45-33828

Property Name West Bisti SWD Well # 1 Location: Unit 7 Sec 35 Twn 26 Rge 13

Land Type:

State _____
Federal _____
Private _____
Indian /

Well Type:

Water Injection _____
Salt Water Disposal /
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: 2-17-2015


Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 55
Int. Casing Pres. N/A

Pressured annulus up to 945 psi. for 30 mins. Test passed/failed

REMARKS:

Fracture Set at 6809

Fracture Set at 6878-7064




By Roy Collison
(Operator Representative)

Witness Monica Dahlberg
(NMOCD)

(Position)

Revised 02-11-02

RCVD FEB 22 '10
OIL CONS. DIV.
DIST. 3



TEST ACCEPTABLE
FOR NMOCB
CR 2-22-10