


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



Release Notification and Corrective Action

30 039 26371

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <b>Phillips Petroleum Company</b>	Contact <input type="checkbox"/> R. A. Wirtanen
Address <b>5525 Hwy. 64 Farmington, NM 87401</b>	Telephone No. <input type="checkbox"/> 505-599-3462
Facility Name <b>San Juan 29-5 #6A</b>	Facility Type <input type="checkbox"/> Gas Well

Surface Owner <b>Fee- Juan Talamante</b>	Mineral Owner <b>FEE</b>	Lease No. <input type="checkbox"/> FEE
---	-----------------------------	--

LOCATION OF RELEASE

Unit Letter <b>D</b>	Section <b>27</b>	Township <b>29N</b>	Range <b>5W</b>	Feet from the <b>790</b>	North/South Line <b>North</b>	Feet from the <b>790</b>	East/West Line <b>West</b>	County <input type="checkbox"/> Rio Arriba
-------------------------	----------------------	------------------------	--------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	--

NATURE OF RELEASE

Type of Release <b>Condensate</b>	Volume of Release <b>5 bbls</b>	Volume Recovered <input type="checkbox"/> 0 (none)
Source of Release <b>Condensate tank - leaking gasket</b>	Date and Hour of Occurrence <b>12/19/01 @ 0800 hrs</b>	Date and Hour of Discovery <input type="checkbox"/> 12/19/01 <b>@ 0800 hrs by Operator Jim Thomas</b>
Was Immediate Notice Given? <b>X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required</b>	If YES, To Whom? <b>NMOCD - Denny Foust via -e-mail.</b>	
By Whom? <b>Patsy Clugston - Sr. Regulatory Clerk</b>	Date and Hour <input type="checkbox"/> 12/21/01 @ 0945 hrs	
Was a Watercourse Reached? <b><input type="checkbox"/> Yes X No</b>	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*  
**A watercourse was not reached.**

Describe Cause of Problem and Remedial Action Taken.\*

**Operator Jim Thomas noticed that the manway gasket was barely leaking, so he attempted to tighten it and as he did the condensate started pouring out. Before he could get it fixed approx. 5 bbls condensate was lost. All the condensate was contained within the bermed area on the location. This volume is estimated by the amount of soil that was excavated.**

Describe Area Affected and Cleanup Action Taken.\* ☐ Operator immediately called A&W Contractors to excavate the soils. Approx. 1 silver bullet was filled and the remainder has been stocked piled & bermed within the location until it can be hauled to Envirotech. The size of the excavation is approx. 20' X 20' X 2' and main spot turned out to be a 6'X4'X4' hole. (35 cubic yards)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Patsy Clugston</i>	OIL CONSERVATION DIVISION	
Printed Name: <b>Patsy Clugston</b>	Approved by <input type="checkbox"/> District Supervisor: <i>Denny Foust for Frank Chavez</i>	
Title: <b>Sr. Regulatory Clerk</b>	Approval Date: <i>12/28/01</i>	Expiration Date:
Date: <b>12/21/01</b> Phone: <b>505-599-3454</b>	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

n DGF0136 229157



LOCATION NAME: SJ 29-5 # 6A Spill Assessment

LEGAL LOCATION: NW/4 Sec 27, T 29 N, R 5 W

DATE DRAWN: 12/21/2001

BY: Virgil Chavez

SKETCH #:


Sample Area	Field Headspace
N Wall @ 1.5'	37.1 ppm
S Wall @ 1.5'	0 ppm
E Wall @ 1.5'	3.1 ppm
W Wall @ 1.5'	26.8 ppm
Bottom @ 2'	12.1 ppm
Bottom @ 6'	77.3 ppm

Total cubic yards excavated = 35

Direction of Flow



Entrance



Source of Spill

Excavated  
5' x 5' x 6' deep

Excavated Area  
20' x 20' x 2' deep

Flow Line

Water  
Tank

Separator



