

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30 045 09 389

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <b>BP (Amoco Production Company)</b>	Contact <b>Brittany Benko</b>
Address <b>200 Energy Court Farmington, NM 87401</b>	Telephone No. <b>(505) 326-9235</b>
Facility Name <b>Ludwick LS 11</b>	Facility Type <b>Wellsite</b>

Surface Owner <b>BLM</b>	Mineral Owner <b>BLM</b>	Lease No. <b>NMSF078194</b>
--------------------------	--------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter <b>B</b>	Section <b>19</b>	Township <b>30N</b>	Range <b>10W</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>San Juan County</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------------------

NATURE OF RELEASE

Type of Release <b>Produced Water</b>	Volume of Release <b>21.65 bbls</b>	Volume Recovered <b>0 bbls</b>
Source of Release <b>Dehydrator</b>	Date and Hour of Occurrence <b>Unknown</b>	Date and Hour of Discovery <b>12/16/2001 7:00 am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Denny Faust</b>	
By Whom? <b>Brittany Benko</b>	Date and Hour <b>12/17/2001 9:10 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The rupture disc on the dehydrator failed causing the unit to release produced water on location. The well was shut-in immediately and the rupture disc was replaced. Further investigation of the failed rupture disc indicated that exposure to weather had caused it to rust and consequently fail. As a result of the investigation, all pumpers will be instructed to cover rupture disc risers and PSVs to protect them from the weather. The timeline for this corrective action is still being discussed.

Describe Area Affected and Cleanup Action Taken.\*

None of the Produced Water left the location/wellpad. The contaminated soil is being landfarmed on site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brittany D Benko</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Brittany D. Benko</i>	Approved by District Supervisor: <i>Denny Faust</i>	for Frank Chavez
Title: <i>Environmental Coordinator</i>	Approval Date: <i>1/03/2002</i>	Expiration Date:
Date: <i>12/31/01</i>	Phone: <i>326-9235</i>	Conditions of Approval: Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

NDG-F0135752740