


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



### Release Notification and Corrective Action

30 045 11071

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company CONOCO INC.	Contact GARY LEDBETTER
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837
Facility Name Newberry LS #5	Facility Type PRODUCTION FACILITY

Surface Owner Lewis Montoya	Mineral Owner BLM	Lease No. SF 078146
--------------------------------	----------------------	------------------------

#### LOCATION OF RELEASE

Unit Letter G	Section 5	Township 31N	Range 12W	Feet from the 1650	North/South Line FNL	Feet from the 1750	East/West Line FEL	County SAN JUAN
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	--------------------

#### NATURE OF RELEASE

Type of Release Motor Oil 40wt.	Volume of Release 190 gals	Volume Recovered 190 gals
Source of Release Above ground Storage Tank	Date and Hour of Occurrence 2/13/01 8:00 am	Date and Hour of Discovery 2/13/01 9:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust	
By Whom? Kevin Romine	Date and Hour 2/13/01 2:10 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A feed line was pulled loose by a cow. The line connected the above ground storage tank and the compressor. Envirotech Inc. was called to the site and Peat Moss was applied.

Describe Area Affected and Cleanup Action Taken.\*

150' X 8' of sage brush cover land. Envirotech removed 25 cubic yards of contaminated soil to their landfarm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: GARY LEDBETTER	Approved by District Supervisor:	
Title: SHEAR SPECIALIST	Approval Date: 03/08/01	Expiration Date:
Date: 3/2/01 Phone: 505-324-5837	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

NDG F0106738195