

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 22764

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Richardson Operating Co.	Contact	John W Whisler
Address	1700 Lincoln, Suite 1700, Denver, Co 80203	Telephone No.	303-830-8000
Facility Name	Ms. Nona #2	Facility Type	Gas Producer

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	NM-28820
---------------	-----	---------------	-----	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section 15	Township 30N	Range 14W	Feet from the 920'	North/South Line FNL	Feet from the 970'	East/West Line FEL	County SAN JUAN COUNTY, NM
-------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	-------------------------------

NATURE OF RELEASE

Type of Release Produced coal seam water	Volume of Release 18 BBL	Volume Recovered 5 BBL
Source of Release Water Injection Line (Vandalism - Someone shut off the valve on line.)	Date and Hour of Occurrence September 16, 2001 6:00 PM	Date and Hour of Discovery September 18, 2001 8:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Denny Foutz	
By Whom? John Durham	Date and Hour Denny Foutz, 9:00 AM Sept. 18	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. *

Describe Cause of Problem and Remedial Action Taken. *

Cause of spill was vandalism. Valve was shut off downstream, which caused line to pressure up and burst.
Repaired line

Describe Area Affected and Cleanup Action Taken *

Clean up consisted of removing coal fines, raking up spill site, and reseeding area
Spill was contained on right of way.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: <i>John W Whisler</i>		OIL CONSERVATION DIVISION	
Printed Name: John W Whisler		Approved by <i>Denny Foutz</i> District Supervisor: <i>for Frank Chavez</i>	
Title: Operations Manager		Approval Date: <i>11/20/01</i>	Expiration Date:
Date: 10/16/01	Phone: 303-830-8000	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DGF 0132449763