

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131


State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C-141
Originated 2/13/97



Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.

Release Notification and Corrective Action

30 045 25040

OPERATOR

☒ Final Report

Name:	Burlington Resources	Contact:	Gregg Wurtz
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9537
Facility Name:	STATE COM 31-8	Facility Type:	Gas Well

Surface Owner:	State	Mineral Owner:	State	Lease Number:	E-1195-11-NM
----------------	-------	----------------	-------	---------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: Rio Arriba
M	02	031N	008W	1225	south	1015	west	

NATURE OF RELEASE

Type of Release:	Coal seam produced water	Volume of Release:	150 BBLS.	Volume Recovered:	70 BBLS.
Source of Release:	Water Storage Tank	Date and Hour of Occurrence:	4/30/2001 5:00:00 PM	Date and Hour of Discovery:	4/30/2001 3:00:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom?	CHARLIE PERRIN		
By Whom?	Gregg Wurtz	Date and Hour:	5/1/2001 3:33:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Vandalism, valve opened on tank. Recovered as much water as practical and raked soil to break crusting on soil.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Approximately 70 bbls outside berm contained and recovered on location with approximately 5 bbls traveling a narrow (1 foot or less) flow path off location 60 yards following natural depression in topography.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name:	Gregg Wurtz	Approved by:	<i>Denny Zent</i>
Title: Environmental Representative		District Supervisor:	<i>for Frank Chavez</i>
Date: 5/1/01	Phone: (505) 326-9841 or 326-9842	Approval Date: 5/16/2001	Expiration Date:
		Conditions of Approval:	Attached: <input type="checkbox"/>

n b g f 0113642834