

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division

2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141
Originated 2/13/97Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.

Release Notification and Corrective Action

3004525923

OPERATOR

☐ Initial Report☒ Final Report

Name:	Burlington Resources	Contact:	GREGG WURTZ
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	
Facility Name:	MCGRATH SWD	Facility Type:	Gas Well

Surface Owner:	Fee	Mineral Owner:	Fee	Lease Number:	
----------------	-----	----------------	-----	---------------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
	34	30N	12W					

NATURE OF RELEASE

Type of Release:	BS&W	Volume of Release:	30 BBLS.	Volume Recovered:	22 BBLS.
Source of Release:	Water Storage Tank	Date and Hour of Occurrence:	6/26/2001 12:30:00 PM	Date and Hour of Discovery:	6/26/2001 12:30:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom?			
By Whom?	Gregg Wurtz	Date and Hour: 6/26/2001 4:00:00 PM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Dawn Trucking driver unloaded transport tanker truck and over flowed storage tank. Remedial action was to recover as much free liquid as possible and remove soil and gravel impacted by BS&W. Removed liquid was put back into system and 10 cu yd soil and gravel landfilled at Tierra Linda farm.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

A total area of 10 feet by 10 feet adjacent to storage tank and filter building floor. Filter building collected approximately 7 bbls in floor drain sump and collection tank remaining 15 bbls vacuume truck recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name:	Gregg Wurtz	Approved by:	<i>Denny Faint</i>
Title: Environmental Representative		District Supervisor:	<i>for Frank Chavez</i>
Date:		Approval Date:	08/03/01
Phone: (505) 326-9841 or 326-9842		Expiration Date:	
Conditions of Approval:		Attached:	<input type="checkbox"/>

n DGF0121044529