

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP (Amoco Production Company)	Contact Brittany Benko	
Address 200 Energy Court Farmington, NM 87401	Telephone No. (505) 326-9235	
Facility Name Arnaud A #1	Facility Type Wellsite	
Surface Owner BLM	Mineral Owner BLM	Lease No. NMSF078513

LOCATION OF RELEASE

Unit Letter H	Section 17	Township 32N	Range 9W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan County
-------------------------	----------------------	------------------------	--------------------	---------------	------------------	---------------	----------------	----------------------------------

NATURE OF RELEASE **4,200 MCF**

Type of Release Uncontrolled Gas Release <i>Net.</i>	Volume of Release 4.2 MMscf	Volume Recovered 0
Source of Release Cooler on the compressor	Date and Hour of Occurrence 12/14/2002 5:00 am	Date and Hour of Discovery 12/16/2002 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie Perrin & Denny Foust (message)	
By Whom? Brittany Benko	Date and Hour 12/17/2002 10:55 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The tube on the compressor cooler failed resulting in an uncontrolled gas release. It appears that the tube failed due to corrosion. The compressor cooler was repaired and the compressor is back in service. All compressors are on a 45-day preventative maintenance schedule. We will continue to maintain this schedule to prevent these problems in the future.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brittany D Benko</i>	OIL CONSERVATION DIVISION	
Printed Name: Brittany D Benko	Approved by District Supervisor: <i>Denny Foust</i>	for Frank Chavez
Title: Field Environmental Coordinator	Approval Date: 01/02/03	Expiration Date:
Date: 12/23/02 Phone: (505) 326 - 9235	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDGF0235336710