


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



Release Notification and Corrective Action

30 045 29348

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Playa Minerals & Energy, Inc.	Contact Ken Jackson
Address 650 N. Sam Houston Pkwy. E. Suite 500 Houston, Texas 77060	Telephone No. (281) 931-3800
Facility Name Northeast Hogback Unit near well #53	Facility Type Oil Lease Tank Battery

Surface Owner Navajo Nation	Mineral Owner Federal	Lease No.
--------------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	10	30N	16W	1500'	South	1000'	East	San Juan

NATURE OF RELEASE

Type of Release Oil and Water	Volume of Release 230 BBls	Volume Recovered 142
Source of Release Middle Stock Tank in Main Tank Battery (Located close to NEHU #53)	Date and Hour of Occurrence 12/25/01 2:00 AM	Date and Hour of Discovery 12/26/01 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bruce Martin	
By Whom? Gene Martin Field Foreman	Date and Hour 12/27/01	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Leak developed in Man Cover Access causing contents of Stock Tank to leak inside the berm.  
Battery shut-in and cover replaced.

Describe Area Affected and Cleanup Action Taken.\*

Oil and Water leaked inside berm. As much oil was recovered as possible. The soil inside the berm will be removed and if necessary replaced with clean soil

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth W. Jackson</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth W. Jackson	Approved by <i>Denise Feart</i> District Supervisor: <i>for Frank Chavez</i>	
Title: Regulatory Compliance	Approval Date: <i>01/09/02</i>	Expiration Date:
Date: 01/02/02 Phone: (281) 931-3800	Conditions of Approval: <i>Submit</i>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

attachment for this report outlining  
cleanup actions taken by February 1, 2002

ADG F 0200335562