

CORRECTED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 29809

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company DAWN TRUCKING / BURLINGTON RESOURCES	Contact DANNY NELSON, JR./ED HAZLEY
Address FARMINGTON, N.M.	Telephone No. (505) 327-6314 / (505) 326-9700
Facility Name N/A	Facility Type N/A


Surface Owner B.L.M.	Mineral Owner FEDERAL/STATE	Lease No. API30045298090000
-------------------------	--------------------------------	--------------------------------

LOCATION OF RELEASE

Unit Letter E	Section 16	Township 32N	Range 6W	Feet from the 1750	North/South Line NORTH	Feet from the 880	East/West Line WEST	County SAN JUAN
------------------	---------------	-----------------	-------------	-----------------------	---------------------------	----------------------	------------------------	--------------------

NATURE OF RELEASE

Type of Release PRODUCTION WATER - FRUITLAND COAL	Volume of Release 3360 GAL.	Volume Recovered 0
Source of Release DAWN WATER TRUCK	Date and Hour of Occurrence 6/9/01 4:00 PM	Date and Hour of Discovery 6/9/01 4:10 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? DENNY FOUST - N.M. O.C.D.	
By Whom?	Date and Hour 6/11/01 8:30 AM	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse +/- 3000 GALLONS	
If a Watercourse was Impacted, Describe Fully.* WATER TRAVELED FROM ROADWAY INTO ARROYO (WATERCOURSE) LENGTH - APPROXIMATE 642 FEET - WIDTH APPROXIMATE 2 FEET		
Describe Cause of Problem and Remedial Action Taken.* DRIVER VIOLATED DAWN POLICY AND ILLEGALLY DISCHARGED PRODUCTION WATER ON ROADWAY AND INTO ARROYO. DRIVER HAS BEEN DISCHARGED. NONE AT THIS TIME.		
Describe Area Affected and Cleanup Action Taken.* PRODUCED WATER SAMPLE BEING TESTED FOR COMPARISON. WAITING FOR FURTHER DIRECTION FROM APPROPRIATE AGENCIES. SEE PHOTOS.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Danny Nelson Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name: DANNY NELSON JR.	Approved by <i>Denny Foust</i> District Supervisor: <i>for Frank Chavez</i>	
Title: VICE PRESIDENT - DAWN TRUCKING CO.	Approval Date: <i>6/25/01</i>	Expiration Date:
Date: 6/12/01 Phone: (505) 327-6314	Conditions of Approval: <i>Simple Contamination</i> Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

NDGFO116454213

*for chlorides, clean-up to WACC
standards or background*