

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Energen Resources, Inc.	Contact: Ed Hasely
Address: 2010 Afton Place, Farmington, NM 87401	Telephone No: 505-324-4131
Facility Name: Chicon Jicarilla D #6	Facility Type: Oil/Gas Well Site

Surface Owner: Jicarilla Apache Tribe	Mineral Owner: Jicarilla Apache Tribe	Lease No. Jicarilla Apache 183
---------------------------------------	---------------------------------------	--------------------------------

LOCATION OF RELEASE

API #30-043-20212

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	21	23N	3W	2310	South	330	East	Sandoval

Latitude 36.20651

Longitude -107.15268

NATURE OF RELEASE

Type of Release: Oil Spill	Volume of Release: 100 bbls	Volume Recovered: 35 bbls
Source of Release: Oil Storage Tank	Date and Hour of Occurrence: 12/14/07	Date and Hour of Discovery: 8:00 am 12/14/2007
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jicarilla EPO - Cordell Tecube, NMOCD - Henry Villanueva, BLM - Mark Kelly (message)	
By Whom? Ed Hasely	Date and Hour 12/14/2007 2:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA RCVD JAN 10 '08	



If a Watercourse was Impacted, Describe Fully.* NA	OIL CONS. DIV. DIST. 3
----------------------------------------------------	---------------------------

Describe Cause of Problem and Remedial Action Taken.*

A hole in the oil storage tank near the bottom allowed the oil to leak out into the bermed area. The hole was plugged and the remaining contents of the tank were removed to prevent further leakage. A vacuum truck was used to recover the free standing liquids. All fluids were contained inside the bermed area.

Describe Area Affected and Cleanup Action Taken.* The oil tank and pit tank were moved so that the soil beneath the equipment can be removed. Impacted soils were excavated and are being transported to a commercial disposal facility. Samples were collected from the excavation and sent to a laboratory for analysis. The samples are below the 100 ppm TPH, so backfilling the excavation with clean soils has begun. Plans are to replace the existing oil storage tank. NOTE: A final report will be submitted with the lab analyses and final volumes.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ed Hasely	Approved by District Supervisor:  For: Charlie Perrier	
Title: Sr. Environmental Engineer	Approval Date: 1-10-08	Expiration Date:
E-mail Address: ed.hasely@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/08/08 Phone: 505-324-4131		

* Attach Additional Sheets If Necessary

nBP0804350676



January 8, 2008

New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, New Mexico 87410
Attn: Henry Villanueva

Re: **Chacon Jicarilla D #6**
Initial Release Report Submittal

Dear Sirs:

Enclosed is an initial Release Notification and Corrective Action (C-141) Form for the recent release on the Chacon Jicarilla D #6. The release was verbally reported to the Jicarilla EPO, the Farmington BLM, and the New Mexico OCD on the day of the incident. The excavation of impacted soils has been completed, but the hauling off of these soils and the backfilling is still in progress. I will follow-up with a final report once the job is complete. The final report will include the lab analyses and the volume of impacted soils that were removed.

If there are any questions or concerns with this submittal, please contact me at 505-324-4131.

Sincerely,

A handwritten signature in black ink, appearing to read "Ed Hasely", with a stylized flourish at the end.

Ed Hasely
Sr. Environmental Engineer
Energen Resources

Attachment: Final C-141
Lab Reports

Cc: Bert Thomas
BLM
Jicarilla EPO
Jicarilla Oil and Gas
Facility File
Correspondence