



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 11/6/03 Operator Burlington Res API # 30-0 45-26470

Property Name Pump Canyon SWD Well # 1 Location: Unit 5 Sec 7 Twn 30 Rge 8

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal X
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____


Pressured annulus up to 540 psi. for 30 mins. Test passed failed

REMARKS: This MIT was not witnessed by OGD staff
Chart provided by Burlington Resources

By _____ Witness _____
(Operator Representative) (NMOCD)

(Position)

Revised 02-11-02



30-045-26970