



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://nemnr.state.nm.us/ood/District/III/3district.htm>

MECHANICAL INTEGRITY TEST REPORT
(TA or UIC)

Date of Test 9-19-2001 Operator Burlington API # 30-0 45-28563

Property Name San Juan 32-9 Well # 5 Location: Unit A Sec 18 Twn 31 Rge 9

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal X
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): N

TA Expires: _____

Casing Pres. -0
Bradenhead Pres. 0
Tubing Pres. -0
Int. Casing Pres. _____


Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. 1627

Pressured annulus up to 336 psi. for 30 mins. Test passed/failed

REMARKS:

Well has been down ~ 1 1/2 months for casing failure.



By Sheldon Montoya
(Operator Representative)

Witness Bruce Math
(NMOCD)

(Position)

REVISED 11-17-98

cc: Mar tsoie

