NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/18/10 **Operator** Energen Resources **API #** 3003906347

Property Name JICARILLA 98 1 **Location:** Unit M Section 19 Township 26 Range 3

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 138 Intermediate _____ Casing 135 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead: BH Blowdown	Bradenhead: Casing Monitor	Bradenhead: Intermediate Monitor	Intermediate: Intermediate Blowdown	Intermediate: Casing Monitor
5 minutes	0	136			
10 minutes	0	136			
15 minutes	0	136			
20 minutes	0	136			
25 minutes	0	136			
30 minutes	0	136			
5 minute SI	0	136			

	Bradenhead Flowed	Intermediate Flowed
Steady Flow	X	
Surges		
Down to Nothing		
No Flow		
Gas	X	
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediat _____

RECEIVED JUN 2010 OIL CONS. DIV. DIST. 3

REMARKS:

By [signature] **Witness** _____

Lease operator

(Position)

NMOCD Test Area: C 478