

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	5/18/10		Operator 	Ener	Energen Resources			3003921238		
Property Nam	ne	JICARILLA 96 5A		Location: Unit D Section 11		Section 11 T	ownship	26	Range	3
		(Well Name	e and Number)						•	
Pressure (Shut-in or Producing) Tubing		Tubing	70 Intermediate		Casing/	Bradenh		ead <u>č</u>	2_	
OPE	N BRADENH	EAD AND	INTERMEDIA	TE TO ATMOS	PHERE IND	IVIDUALLY FOR	15 MINUT	res e	ACH	••••••
	Bradenhead			Interme	diate		Bradenhead		Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flow		Flowe	
5 minutes	0	100				Steady Flow				
10 minutes	0	100				Surges				
15 minutes	0	100				Down to Nothing				
20 minutes						No Flow				
25 minutes						Gas				
30 minutes						Gas and Water	·			
5 minute SI	0	100				Water				
If bradenho Clear 5 Minute Si REMARKS:	F:	vater, che resh _ radenhea	eck all of the de		t apply belo	<u>ow:</u> Bla	OIL COM	31- -CE - W. 20 - S. DIV. 1	VED NO. A.	29101779
		·								
		· ·								
By John	I M	ahor		Wi	tness			J-11 .		
	7	(Positior	1)							