



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 5-12-10 Operator Adon API #30-0 3921696  
Property Name NEBU Well No. 18A Location: Unit \_\_\_\_\_ Section 9 Township 30<sup>N</sup> Range 7<sup>W</sup>  
Well Status(Shut-In or Producing) Initial PSI: Tubing 30 ~~Intermediate~~ Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead <del>Int</del>	Csg	<del>INTERM</del> Int	Csg
TIME					
5 min	<u>0</u>	<u>-</u>	<u>70</u>		
10 min	<u>0</u>	<u>-</u>	<u>70</u>		
15 min	<u>0</u>	<u>-</u>	<u>70</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<input checked="" type="checkbox"/>
Nothing	
Gas	<input checked="" type="checkbox"/>
Gas & Water	
Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE \_\_\_\_\_

REMARKS:

By James L. Winters  
Tester  
(Position)

Witness

Adon

E-mail address \_\_\_\_\_

