



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.d.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 5-7-10 Operator Sevon API #30-0 3924217
Property Name NEBU Well No. 407 Location: Unit Section 21 Township 30^N Range 7R
Well Status(Shut-In or Producing) Initial PSI: Tubing 11 Intermediate Casing 4 Bradenhead 22

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	20	-	4		
10 min	20	-	4		
15 min	20	-	4		
20 min	20	-	4		
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow ☒	
Surges ☐	
Down to Nothing ☐	
Nothing ☐	
Gas ☒	
Gas & Water ☐	
Water ☐	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: BRADen Head Blew Down when valve was shut Press.
Back to 20 PSI. Imidiatly

By James L. Winters
Tester
(Position)

Witness John [Signature]

E-mail address