



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrld.state.nm.us/ocd/District III/3distric.htm](http://emrld.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-10-10 Operator Devon API #30-0 39224491
Property Name NEBU Well No. 405 Location: Unit Section 21 Township 30N Range 7W
Well Status (Shut-In or Producing) Initial PSI: Tubing 180 Intermediate Casing 180 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead	Int	Csg	Int	Csg
TIME	BH	Int	Csg		
5 min	0	-	180		
10 min	0	-	180		
15 min	0	-	180		
20 min	0	-	180		
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD ~~INTERMEDIATE~~

Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

By [Signature]
Tester
(Position)

Witness [Signature]

E-mail address

