

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(,		
Date of Test	5/	<u> 5 /21 /10</u> Operat		Energen Resources			API# 300	3925305
Property Nam	e	JICARILLA 98 10A		Location: Unit J Section 17		Section 17 T	ownship 26	Range 3
		(Well Name	and Number)					
Pressure (Sh	ut-in or Proc	ducing)	Tubing _	170 Interme	diate	Casing/	70 Bradenh	ead <u>O</u>
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH
	Bradenhead			Interme	diate]	Bradenhead	Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	170				Steady Flow		
10 minutes	0	170				Surges		
15 minutes	0	170				Down to Nothing		
20 minutes						No Flow	X	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	170				Water		
If bradenhe Clear 5 Minute Sh	Fı	resh	Sa	escriptions tha	t apply bel Sulfur	<u>ow:</u> Bla	25.25.25.25.25.25.25.25.25.25.25.25.25.2	031 723 8567897077 CLIVED WORTS SEE
By Leas	C OREMO	hv		Wit	tness			

(Position)