

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/18/10 Operator Energen Resources API # 3003927412

Property Name JICARILLA 99 18 **Location:** Unit F Section 14 Township 26 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 60 Intermediate _____ Casing 90 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	90				Steady Flow		
10 minutes	0	90				Surges		
15 minutes	0	90				Down to Nothing		
20 minutes						No Flow	X	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	90				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead Intermediat

REMARKS:

By Mr. Mr.

Witness _____

(Position)

