NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-11-10 Operator Devon API #30-0 3927702

Property Name NEBU Well No. 411A Location: Unit ___ Section 10 Township 30N Range 7W

Well Status(Shut-In or Producing) Initial PSI: Tubing 17 Intermediate 8 Casing 7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0	8	7	5	7
10 min	0	8	7	7	7
15 min	0	8	7	8	7.4
20 min	0	8	7	8	8
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		✓ 3PSI. Flow
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	✓
Gas & Water		
Water		

RECEIVED MAY 2010 OIL CONS. DIV. DIST 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 5

REMARKS: 3PSI. Steady Flow - Shut in 5min 5PSI

By James A. Winters
Tester
(Position)

Witness [signature] - Devon

E-mail address ___