



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/HU3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-12-10 Operator Devon API #30-0 3927750
Property Name NEBU Well No. 4034 Location: Unit Section 9 Township 30N Range 7W
Well Status (Shut-In or Producing) Initial PSI: Tubing 10 Intermediate Casing 8 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	7	-	6		
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow ☒	
Surges ☐	
Down to Nothing ☐	
Nothing ☐	
Gas ☒	
Gas & Water ☐	
Water ☐	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

2 Braden Head Valves - Bleeddown To 6 PSI Steady Flow
Both Valves showed mirror Readings

By Paul Winters
Tester
(Position)

Witness

Allen - Devon

E-mail address

