



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energex Resources API # 3003930121

Property Name JICARILLA 117 E 5C Location: Unit K Section 28 Township 26 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 220 Intermediate        Casing 230 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>230</u>				Steady Flow	
10 minutes	<u>0</u>	<u>230</u>				Surges	
15 minutes	<u>0</u>	<u>230</u>				Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	<u>0</u>	<u>230</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur        Black       

5 Minute Shut-in Bradenhead 0 Intermediate       

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By [Signature]

Witness       

Lease operator

(Position)

