UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** JUN 0 1 2010

Kroeinem

Bureau of Land Management Farmington Field Office

	Sundry Notices and Reports on Wells		
1	Type of Well	5. 6.	Lease Number SF-079302-A If Indian, All. or
1.	GAS	0.	Tribe Name
2.	Name of Operator	7.	Unit Agreement Name
	BURLINGTON RESOURCES OIL & GAS COMPANY LP		
3.	Address & Phone No. of Operator	8.	Well Name & Number Sanchez A 3
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
4.	Location of Well, Footage, Sec., T, R, M	•	30-039-20096
		10.	Field and Pool
	Surf: Unit O (SWSE), 1180' FSL & 1650' FEL, Section 20, T26N, R6W, NMPM		Chacra County and State Rio Arriba, NM
12.	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT	HER I	DATA
	Type of Submission Type of Action Notice of Intent Abandonment Change of Plans		Other - Plug PC
	Recompletion New Construction X Subsequent Report X Plugging Non-Routine Fracturing Casing Repair Water Shut off		ROVD JUN 3'10
2	Final Abandonment Altering Casing Conversion to Injection		OIL CONS. DIV.
13.	Describe Proposed or Completed Operations		52% AX 75
5/1	8/10 Burlington Resources Plugged Back the PC side of this duel completion. This is a Chacr	ra stand	alone.
14.	I hereby-certify that the foregoing is true and correct.		
Sig	ped Nonda Rogers Title Staff Regula	tory Te	echnician Date 6/1/10.
	is space for Federal or State Office use) PROVED BY Title		Date
CO Title	NDITION OF APPROVAL, if any: 18 USC Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of inted States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction		

AGREPAED FOR RECORD JUN 0 2 2010 PARMINGTON FIELD OFFICE



A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

Burlington Resources
Sanchez A #3

May 19, 2010 Page 1 of 2

1180' FSL & 1650' FEL, Section 20, T-26-N, R-6-W Rio Arriba Country, NM Lease Number: SF-079302-A API #30-039-20096

Plug and Abandonment Report

Notified BLM and NMOCD on 5/10/10

- 05/11/10 MOL. Spot rig. LO/TO equipment. Lay relief lines. RD separator, ready for removal. Dig out bradenhead. RD wellhead. SDFD due to high winds.
- 05/12/10 RU rig. Check well pressure: PC casing on vacuum; Chacra casing, 70 PSI; bradenhead, 0 PSI. Casing strings identified by meter run EFM's). Round trip 2.25" gauge ring and tag fill at 2934' on PC casing. RIH with 2.875" CIBP and set at 2860'. NU BOP, test. TIH and tally 93 joints 1.25" HSH tubing and tag CIBP at 2860'. SI well. SDFD.
- 05/13/10 Check well pressure: tubing, 10 PSI; casing and bradenhead, 0 PSI. Load the hole with 3 bbls of water. Circulate well clean with additional 14 bbls of water. Attempt to pressure test casing 1 bpm at 600 PSI, no test.

Plug #1 with CIBP at 2860', spot 23 sxs Class B cement (27.14 cf) inside casing above CIBP up to 2025' to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops. TOH with tubing. SI well and WOC. TIH with tubing and tag cement low at 2454'. Load the hole with 13 bbls of water and circulate well clean.

Plug #1a spot 13 sxs Class B cement (15.34 cf) inside casing from 2454' up to 1982' to cover the Kirtland and Ojo Alamo tops.

TOH with tubing. Note: casing and bradenhead blowing. SI well. SDFD.

05/14/10 Check well pressure: PC casing, 5 PSI; Chacra casing, 95 PSI; bradenhead, 0 PSI. Blow PC casing down to pit. TIH with tubing and tag cement at 2068'. PUH to 1107'. Connect pump to tubing and load the hole with 3 bbls of water. Attempt to pressure test casing 1 bpm at 600 PSI, no test.

Plug #2 with 17 sxs Class B cement (20.06 cf) inside casing from 1107' up to 409' to cover the Nacimiento top.

TOH with tubing. SI well and WOC. TIH with tubing to 1107', no cement. Connect pump to tubing and load the hole with 2.5 bbls of water. Circulate well clean with additional 4-1/2 bbls of water. About ½ bbl wet cement in returns. Attempt to pressure test casing 1 bpm at 600 PSI, no test.

Plug #2a with 16 sxs Class B cement (18.88 cf) inside casing from 1107' up to 527' to cover the Nacimiento top.

TOH with tubing. SI well. SDFD.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

Burlington Resources Sanchez A #3

May 19, 2010 Page 2 of 2

Plugging Summary – Continued:

05/17/10 Check well pressure: PC casing, 0 PSI; Chacra casing, 95 PSI; bradenhead, 0 PSI. TIH and tag cement at 602'. PUH to 183'. Load casing with 2-1/2 bbls of water. Attempt to pressure test casing 1 bpm at 100 PSI, no test.

Plug #3 with 16 sxs Class B cement (18.88 cf) down the 2.875" PC casing from 183' to surface, circulate good cement out the casing valve.

TOH and LD all tubing. SI well and WOC. Attempt to pressure test casing 1 bpm at 100 PSI, no test. TIH to 210', no cement.

Plug #3a with 16 sxs Class B cement (18.88 cf) down the 2.875" PC casing from 210' to surface, circulate good cement out the casing valve. SI well and WOC. TIH and tag cement at 61'. SDFD.

0518/10 Check well pressure: PC casing, 0 PSI; Chacra casing, 95 PSI; bradenhead, 0 PSI. TIH with tubing and tag cement at 61'. Pressure test 2.875" casing to 30 PSI, bled down to 0 PSI in 1.5 minutes.

Plug #3b with 8 sxs Class B cement (9.44 cf) down the 2.875" PC casing from 61' to surface, circulate good cement out the casing valve.

ND BOP from PC casing. NU BOP on Chacra casing. Blow down casing to 10 PSI, would not blow down completely. Kill well with 15 bbls of water. TIH with 115 joints 1.25" EUE tubing, EOT at 3540' with 12' KB. TOH and LD all tubing. Chacra casing clear to 3540'. SI well. ND BOP. Top off PC casing with cement and install tapped bull plug.

RD rig. MOL.

Jim Yates and Pete McNeal, BROG representatives, were on location.

Walter Gage and Wanda Weatherford, BLM representatives, were on location.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington Field Office 1235 La Plata Highway, Suite A Farmington, New Mexico 87401

IN REPLY REFER TO

NMSF-079302A (WC) 3162.3-2 (21110)

May 27, 2010

CONOCO PHILLIPS

Ms. Sharon Zubrod Burlington Resources Oil & Gas Co. PO Box 4289 Farmington, NM 87499

JUN - 1 2010

Dear Ms. Zubrod:

FARMINGTON, NEW MEXICO REGULATORY

Reference is made to your well No. 3 Sanchez A located 1180' FSL & 1650' FEL Sec. 20, T. 26 N., R. 6 W., Rio Arriba County, New Mexico lease NMSF-079302A. Also referenced is your Sundry Notice dated March 17, 2010, which stated the Pictured Cliffs side of the subject well would be plugged and abandoned by May 15, 2010. If the well has been plugged, you are required to submit a subsequent report of abandonment. If the well has not been plugged, you are required to plug the well as approved and submit a subsequent report of abandonment by June 15, 2010.

Failure to comply within the time above may result in an assessment in accordance with 43 CFR 3163.1.

Under provisions of 43 CFR 3165.3, you may request an Administrative Review of the orders described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice and must be filed with the State Director, Bureau of Land Management, P. O. Box 27115, Santa Fe, New Mexico 87502-0115. Such requests shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders or decisions are contained in 43 CFR 3165.4 and 43 CFR 4.400 et seq.

If you have any questions please contact Stephen Mason with this office at (505) 599-6364.

Sincerely,

Stephen Mason

Petroleum Engineer; Petroleum Management Team