

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	5-2	5 - 21 - 10 Operator			Energen Resources			API# 300	3003905261	
Property Nam	e	JICARILLA P 5				Location: Unit B Section 34		ownship 24	Range 5	
•		(Well Name	and Number)							
Pressure (Sh	ut-in or <u>Proc</u>	lucina).	Tubing _	70	Interme	diate	Casing	Bradenh	nead <u></u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOSE	PHERE IND	DIVIDUALLY FOR	15 MINUTES E	ACH	
	Bradenhead			Intermediate				Bradenhead	Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor		ermediate lowdown	Casing Monitor		Flowed	Flowed	
5 minutes	-	71					Steady Flow			
10 minutes	0	71					Surges			
15 minutes	Ð-	71					Down to Nothing			
20 minutes					·		No Flow	×		
25 minutes							Gas		<u> </u>	
30 minutes							Gas and Water			
5 minute SI	0	71					Water			
If bradenhead flowed water, check all of the descriptions that apply below: Clear Fresh Salty Sulfur Blace 5 Minute Shut-in Bradenhead Intermediat								HECK RECK SOLL CONS	EIVED 2010	
REMARKS: NOTHINH ON BRADEN HEAD.								OF CONS. DIV. DIST. 3		
						16				
ву <u>5</u> 15		PSEX			Wit	tness				

(Position)