



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-10 Operator Energen Resources API # 3003905540

Property Name JICARILLA H 15 Location: Unit K Section 8 Township 24 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing)            Tubing 31 Intermediate            Casing 94 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>94</u>				Steady Flow		
10 minutes	<u>0</u>	<u>94</u>				Surges		
15 minutes	<u>0</u>	<u>94</u>				Down to Nothing		
20 minutes						No Flow	<u>X</u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	<u>0</u>	<u>94</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear            Fresh            Salty            Sulfur            Black           

5 Minute Shut-in Bradenhead 0 Intermediat           

REMARKS:

NOTHING ON BRADENHEAD.

By

S. T. [Signature]  
LEASE OPERATOR

(Position)

Witness

