



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-10 Operator Energen Resources API # 3003905663

Property Name JICARILLA H 5 Location: Unit C Section 6 Township 24 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 100 Intermediate Casing 101 Bradenhead TSTM

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>101</u>				Steady Flow		
10 minutes	<u>0</u>	<u>101</u>				Surges		
15 minutes	<u>0</u>	<u>101</u>				Down to Nothing	<u>X</u>	
20 minutes						No Flow		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	<u>TSTM</u>	<u>101</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead TSTM Intermediate

REMARKS:

BRADENHEAD BLEW DOWN TO NOTHING.

By [Signature]

Witness

LEASE OPERATOR

(Position)

