



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energen Resources API # 3003906138

Property Name MCCRODEN B 2 Location: Unit 1 Section 4 Township 25 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 25 Intermediate      Casing 25 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	25				Steady Flow		
10 minutes	0	25				Surges		
15 minutes	0	25				Down to Nothing		
20 minutes						No Flow	X	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	25				Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear      Fresh      Salty      Sulfur     

5 Minute Shut-in Bradenhead 0 Intermediat     

REMARKS:

Well flowing



By Amador Llanos

Witness     

Sr. Lease operator  
(Position)