



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/2010 Operator Energex Resources API # 3003906968

Property Name JICARILLA 94 5 Location: Unit M Section 23 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 165 Intermediate NA Casing 125 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>175</u>					Steady Flow	
10 minutes	<u>0</u>	<u>175</u>					Surges	
15 minutes	<u>0</u>	<u>175</u>					Down to Nothing	☒
20 minutes							No Flow	
25 minutes							Gas	☒
30 minutes							Gas and Water	
5 minute SI	<u>1</u>	<u>175</u>					Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐ Fresh ☒ Salty ☐ Sulfur ☐ Black ☐

5 Minute Shut-in Bradenhead 1 Intermediate ☐

REMARKS:

Blow Down right away

By Ed Moore

Witness _____

Pumper
(Position)

