



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/20/2010 Operator Energen Resources API # 3003907044

Property Name JICARILLA 89 3 Location: Unit M Section 15 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 120 Intermediate NA Casing 128 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>128</u>				Steady Flow		
10 minutes	<u>0</u>	<u>128</u>				Surges		
15 minutes	<u>0</u>	<u>128</u>				Down to Nothing	<input checked="" type="checkbox"/>	
20 minutes						No Flow		
25 minutes						Gas	<input checked="" type="checkbox"/>	
30 minutes						Gas and Water		
5 minute SI	<u>0</u>	<u>128</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐ Fresh ☐ Salty ☐ Sulfur ☐ Black ☐

5 Minute Shut-in Bradenhead 0 Intermediate ☐

REMARKS:

blew down right away

By Ed Mann

Witness

Pamper
(Position)

