



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/21/2010 Operator Energex Resources API # 3003922879

Property Name JICARILLA 89 7 Location: Unit N Section 13 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 190 Intermediate N/A Casing 240 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>240</u>				Steady Flow		
10 minutes	<u>0</u>	<u>240</u>				Surges		
15 minutes	<u>0</u>	<u>240</u>				Down to Nothing		
20 minutes						No Flow	☒	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	<u>0</u>	<u>240</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

By PH Moore

Witness _____

(Position)

