

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test		5-18-10 Operator		Energen Resources			API# 3003922973	
Property Nam	e	JICARILLA 67 17			Location: Unit C Section 29			25 Range 5
		(Well Name	and Number)					
Pressure (Sh	ut-in or <u>Proc</u>	lucing)	Tubing 🗘	Interme	diate	Casing	OZ Brad	lenhead
OPEN	I BRADENHI	EAD AND	INTERMEDIAT	E TO ATMOSF	PHERE IND	IVIDUALLY FOR	R 15 MINUTE	S EACH
Ţ	Bradenhead			Interme				
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Bradenhe Flowed	ead Intermediate
5 minutes	2	102				Steady Flo	w	
10 minutes	D	102				Surge		
15 minutes	0	102				Down to Nothin	· ——/	<u> </u>
20 minutes						No Flo		
25 minutes				-		Ga		
30 minutes						Gas and Wate		
5 minute SI	₽-	102				Wate	er	990 31 - 123
If bradenhe Clear 5 Minute Sh	Fr	rater, che resh radenhead	Ck all of the de		t apply belo		(10)	RECEIVED JUN 2010 JUN 2010 OZ61 81 L194 CHANG
REMARKS:	BR4DK11	KAD	BLEW A	SOFT BU	on De	00 hw	NOTHIA	Jh. TSTM.
ву <u>5</u> (г	大 45 6 (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	tor.	Wit	tness			

(Position)