



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energen Resources API # 3003923245

Property Name MCCRODEN A 5 Location: Unit J Section 8 Township 25 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 45 Intermediate Casing 110 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	110				Steady Flow		
10 minutes	0	105				Surges		
15 minutes	0	105				Down to Nothing	X	
20 minutes						No Flow		
25 minutes						Gas	X	
30 minutes						Gas and Water		
5 minute SI	0	105				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

well flowing

By Amadio Monzon

Witness

Gr. Lease Operator

(Position)

