



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-17-10 Operator Energen Resources API # 3003923942

Property Name JICARILLA L 8 Location: Unit P Section 33 Township 25 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 44 Intermediate        Casing 88 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	Ø	88										
10 minutes	Ø	87										
15 minutes	Ø	87										
20 minutes												
25 minutes												
30 minutes												
5 minute SI	Ø	87							X			

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur       

5 Minute Shut-in Bradenhead Ø Intermediate       

REMARKS:

NOTHING ON BRADENHEAD. WELL FLOWING.

By [Signature]

Witness       

LEASE OPERATOR

(Position)

