

Date of Test

5/18/10

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

Operator

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

API#

3003927081

BRADENHEAD TEST REPORT

Energen Resources

(Submit 2 copies to above address)

Property Nam	ne FL	FLORANCE FEDERAL 7B			n: Unit B	Section 4 To	ownship 25	Range 3
	·	(Well Name and Number)						
Pressure (Sh	ut-in or Pro	ducing)	Tubing	ど Interme	diate	Casing/ c	<u>ාර</u> Bradenh	ead <u>O</u>
OPE	N BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSE	HERE IND	IVIDUALLY FOR 1	5 MINUTES E	ACH
Bradenhead				Intermediate			Bradenhead	Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minu te s	0	100				Steady Flow		
10 minutes	0	100	1			Surges		
15 minutes	0	100				Down to Nothing		
20 minutes						No Flow		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	110	1.			Water		
If bradenhead flowed water, check all of the descriptions that apply below: Clear Fresh Salty Sulfur Black								
5 Minute Shut-in Bradenhead O Intermediat OIL CONS. DIV. DIST 3								
REMARKS:	well	on	OSF	Cycle		<u>.</u>	ce150561	81 (1 91 ct.)
					- 10 to 10 t			
By AN	alio	M	ason	Wit	ness			
31	heas-	c 0	perator					•
		(Position						