



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/18/10 Operator Energen Resources API # 3003929296

Property Name JICARILLA 117 E 3B Location: Unit L Section 34 Township 26 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 75 Intermediate Casing 100 Bradenhead 757m

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>100</u>				Steady Flow		
10 minutes	<u>0</u>	<u>102</u>				Surges		
15 minutes	<u>0</u>	<u>102</u>				Down to Nothing	<u>X</u>	
20 minutes						No Flow		
25 minutes						Gas	<u>X</u>	
30 minutes						Gas and Water		
5 minute SI	<u>0</u>	<u>110</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

Well on off cycle

By [Signature]

Witness

Tr. Lease Operator

(Position)

