



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-25-10 Operator Energen Resources API # 3003924416

Property Name CARRACAS UNIT FR 111 Location: Unit D Section 33 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 130 Intermediate N/A Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>40</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>		<u>N/A</u>
10 minutes	<u>0</u>	<u>40</u>					
15 minutes	<u>0</u>	<u>40</u>					
20 minutes	<u>0</u>	<u>40</u>				<u>X</u>	
25 minutes	<u>0</u>	<u>40</u>					
30 minutes	<u>0</u>	<u>40</u>					
5 minute SI	<u>0</u>	<u>57</u>					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Jon Hardy Witness _____

Lease Operator

(Position)

