



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-25-10 Operator Energen Resources API # 3003924420

Property Name CARRACAS UNIT 21 B 13 Location: Unit M Section 21 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 140 Intermediate N/A Casing 55 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	55	N/A	N/A	N/A	Steady Flow	N/A
10 minutes	0	55				Surges	
15 minutes	0	55				Down to Nothing	
20 minutes	0	55				No Flow	X
25 minutes	0	55				Gas	
30 minutes	0	55				Gas and Water	
5 minute SI	0	79				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Jim Sandy Witness _____
Lease Operator
(Position)

