



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-25-10 Operator Energen Resources API # 3003926480

Property Name CARRACAS 29 B 8 Location: Unit H Section 29 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 40 Intermediate N/A Casing 41 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	41	N/A	N/A	N/A		N/A
10 minutes	0	41					
15 minutes	0	41					
20 minutes	0	41					
25 minutes	0	41					
30 minutes	0	41					
5 minute SI	0	52					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	X
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By

Jon Hardy

Witness

(Position)

