



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-30-10 Operator Burlington Res API #30-0 45-11431
Property Name Allison Ut. Well No. 9 Location: Unit Section 13 Township 32 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 266 Intermediate 3 Casing 3 Bradenhead 15

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min		3	3		3
10 min		3	3		3
15 min		3	3		3
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>1 fumes</u>	<u>1 fumes</u>
Surges		
Down to Nothing		
Nothing		
Gas	<u>1</u>	<u>1</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

RCVD JUN 30 '10

OIL CONS. DIV.

DIST. 3

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: This well is a POW light blow at 54 seconds - fumes
at 2 min - fumes resting 15 minutes
Int. Hard blow just 15 min. to light blow w/ fumes at 5 minutes
light blow w/ fumes at 10 min.
By [Signature] Witness Monica Kullberg
fumes - really light blow at 15 min

(Position)

E-mail address