



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1008 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://www.nmwr.com/aztec/District 3.htm](http://www.nmwr.com/aztec/District%203.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/27/10 Operator ELMROGUE EXP. API #30-039-82311

Property Name JICARILLA A 156 Well No. 4 Location: Unit 7 Section 1 Township 23N Range 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 45 Intermediate N/A Casing 66 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead		INTERM	BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	0				
10 min					
15 min					
20 min					
25 min					
30 min					

Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By LOYD INGRAM

Witness _____

Pumper
(Position)

E-mail address _____

