

5053279207

Benson-Montin-Greer

03:37.34 p.m. 07-20-2010



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
4000 RIO BRAZOS ROAD
AZTEC, NM 87410
(808) 334-6170 FAX: (808) 854-6170
<http://enmrq.state.nm.us/ocd/District1118/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/10 Operator Benson Montin Greer API #30-0 39-06023Property Name CO-4 Well No. 3 Location: Unit A Section 14 Township 25N Range 1WWell Status (Shut-In or Producing) Initial PSI: Tubing 92 Intermediate N/A Casing 103 Bradenhead 18

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead		INTERM			
	BH	Int		Int	Csg	
TIME						
5 min	0		105			
10 min	0		109			
15 min	0		115			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____REMARKS: Down to nothing in 38 sec.By Ben L. Stofalo

Witness _____

(Position)

E-mail address _____

