



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/23/10 Operator Energen Resources API # 3003907990

Property Name SAN JUAN 32 5 UNIT 14 Location: Unit H Section 26 Township 32 Range 6

(Well Name and Number)

Pressure (Shut-in) or Producing Tubing 155 Intermediate N/A Casing 160 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	160		N/A		Steady Flow	
10 minutes	0	160				Surges	
15 minutes	0	160				Down to Nothing	
20 minutes						No Flow	✓ N/A
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A



REMARKS:

By Alan Kurb
Senior Lease Operator
(Position)

Witness _____