



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX. (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/3/10 Operator Energen Resources API # 3003907992

Property Name SAN JUAN 32 5 UNIT 7 Location: Unit C Section 26 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 75 Intermediate N/A Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>75</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow		
10 minutes	<u>0</u>	<u>75</u>				Surges		
15 minutes	<u>0</u>	<u>75</u>				Down to Nothing		
20 minutes						No Flow	<u>/</u>	<u>N/A</u>
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Alan Kunt Witness _____
Senior Lease Operator
(Position)

