



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test: 2-12-10 Operator: RESOURCE DEVELOPMENT TECHNOLOGY, LLC API #30-039-20549

Property Name: OLD ROCK FED COM Well No. 2 Location: Unit P Section 28 Township 25N Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing: 100 Intermediate: NA Casing: 125 Bradenhead: 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Testing Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH	Int	Csg	Int	Csg		Flowed	Flowed
5 Min	<u>0</u>	NA	<u>125</u>	NA	NA	Steady Flow		NA
10 Min	<u>0</u>	NA	<u>145</u>	NA	NA	Surges		NA
15 Min	<u>0</u>	NA	<u>148</u>	NA	NA	Down to Nothing		NA
20 Min	<u>0</u>	NA	<u>150</u>	NA	NA	Nothing	<u>X</u>	NA
25 Min	<u>0</u>	NA	<u>150</u>	NA	NA	Gas		NA
30 Min	<u>0</u>	NA	<u>150</u>	NA	NA	Gas & Water		NA
						Water		NA

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE: NA

REMARKS:

Row Piston during BH Test - Good - Left Shut

By: Art Sullivan

Witness _____

Lease Operator -- Pumper
(Position)

E-mail address: lizard3s@wildblue.net

