

5053279207

Benson-Montin-Greer

03:37:34 p.m.

07-20-2010



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1006 RIO BRAZOS ROAD
AZTEC NM 87410
(805) 334-8178 FAX: (808) 334-0170
<http://omrpd.state.nm.us/oed/District/IVS/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/10 Operator Benson Montin Greer API #30-0 39-23830Property Name CDU Well No. 28 Location: Unit B Section 29 Township 25N Range 1WWell Status (Shut-In or Producing) Initial PSI: Tubing 50 Intermediate N/A Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing X

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD INTERMEDIATE

REMARKS:

By Bentley GreerWitness

(Position)

E-mail address 