



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 6-11-10 Operator Energen Resources API # 3003924160

Property Name CARRACAS UNIT FR 115 Location: Unit M Section 35 Township 32 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing SS# Intermediate N/A Casing 110# Bradenhead D#

**OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH**


Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0#	110#	N/A	N/A	N/A							
10 minutes	0	110										
15 minutes	0	110						<input checked="" type="checkbox"/>				
20 minutes	0	110										
25 minutes	0	110										
30 minutes	0	110										
5 minute SI	0#	135#										

**If bradenhead flowed water, check all of the descriptions that apply below:**

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0# Intermediate N/A CSG-1SD

REMARKS:



By Michael Howe Witness \_\_\_\_\_  
Sr. Lease Operator  
(Position)