



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-3-2010 Operator Energen Resources API # 3003924169

Property Name Carracas Unit FR #112 Location: Unit E Section 34 Township 32N Range 5W
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 180 Intermediate NA Casing 205 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>205</u>				Steady Flow	
10 minutes	<u>0</u>	<u>205</u>				Surges	
15 minutes	<u>0</u>	<u>205</u>				Down to Nothing	
20 minutes	<u>0</u>	<u>205</u>				No Flow	
25 minutes	<u>0</u>	<u>205</u>				Gas	
30 minutes	<u>0</u>	<u>205</u>				Gas and Water	
5 minute SI	<u>0</u>	<u>205</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS: BH had 10 psig upon arrival - Quick puff when valve was opened, then no flow or build through the test.

By Jon Nobis
Lease operator
(Position)

Witness

