



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-24-2010 Operator Energen Resources API # 3003924284

Property Name CARRACAS UNIT 23 A 2 Location: Unit B Section 23 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 0 Intermediate NA Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>22</u>				Steady Flow <u>0</u>	
10 minutes	<u>0</u>	<u>21</u>				Surges <u>0</u>	
15 minutes	<u>0</u>	<u>22</u>				Down to Nothing <u>0</u>	
20 minutes	<u>0</u>	<u>23</u>				No Flow <u>0</u>	
25 minutes	<u>0</u>	<u>22</u>				Gas <u>0</u>	
30 minutes	<u>0</u>	<u>21</u>				Gas and Water <u>0</u>	
5 minute SI	<u>0</u>	<u>23</u>				Water <u>0</u>	


If bradenhead flowed water, check all of the descriptions that apply below:

Clear NA Fresh NA Salty NA Sulfur NA Black NA

5 Minute Shut-in Bradenhead 0 Intermediate 0

REMARKS: Value is a little sticky But works on
The Bradenhead through the hole fast

By [Signature]
Lease operator
(Position)



NMOCD Test Area: C